

OFFICE OF THE EXECUTIVE ENGINEER
RURAL WORKS DIVISION, BALASORE

No- 6110 /dt- 30.05.2020

To.

The Principal,
Sidhhivinayak Public School,
Judhithirpur, Balasore.

Sub:- Issue of safety certificate in favour of Sidhhivinayak Public School

Ref:- Ltr. No. 119, dtd.29.05.2020 of Asst. Executive Engineer,
R.W. Sub-Division, Balasore

Sir,


With reference to the letter and above cited subject, it is to state that the Asst. Executive Engineer, R.W. Sub- Division, Balasore has been visited the site of above mentioned school which is situated in the village Judhithirpur over Plot No.277/568/817 having Kisam Gharbari total area Ac2.00Dec in the district of Balasore and the inspection report of Asst. Executive Engineer, R.W. Sub- Division, Balasore attached herewith.

As per observation of concerned A.E.E. and eye estimation the building is Four storeyed (G+3) with group pile foundation on report of the Principal of school. The roof of the entire structure is RCC and walls are made with fly ash brick having wooden shutters, windows are done with aluminium framing having glass panel. The floors of the building are finished with different type tiles and also in good condition.

Hence on the basis of present structural condition there is no problem for functioning of educational institution in the said building.

This is for your information and necessary action.

Yours faithfully


30/5
Executive Engineer
R.W. Division, Balasore

Memo No. _____ /dt _____

Copy to the Asst. Executive Engineer, R.W. Sub- Division, Balasore for information and necessary action.


Principal
Siddhi Vinayak Public School
Balasore

cll
Executive Engineer
R.W. Division, Balasore

OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER,
RURAL WORKS SUB-DIVISION, BALASORE.

1158
29/5/20

NO 119 /Dt. 29/5/20 /
TO

The Executive Engineer,
R.W.Division, Balasore .

Sub :- Issue of Building Safty Certificate in favour of siddhivinayak Public School.

Ref:- Your Memo No -7317 dt. 9.10.2019.

In inviting a kind reference to the subject cited above and letter under reference I have visited the said building on dated 26.5.2020 which is situated in the village Judhistirpur. Over Plot No-277/568/817 having gharawadi Kisam in the district of Balasore . It is to mention here that the total Area of the school premises is A 2.00.


EB
29/5

As per eye estimation it is observed that the building is a four storeyed building (G + 3) having framed structure with group pile foundation (as reported by the principal of the School) . The roof of the entire building is RCC Structure and walls are made with ^{fly ash bricke having} wooden shutters, windows are done with alluminium framing having glass pannel . Floors are finished with different type of tiles and also in good condition . It seems that there will be nothing any problem for functioning of educational institution in the said building basing on the present structural condition.

This is for favour of your kind information and necessary action .

Yours faithfully,


Principal
Siddhi Vinayak Public School
Balasore


Asst. Executive Engineer,
R.W.Sub-Division, Balasore